


# Particle Size Chart

## HOW DOES IT WORK?

Large dust particles are carried to the deepest part of the pleat, while smaller particles lodge in the sides. The tremendous amount of filter surface area means high dust-holding capacity with minimum airflow resistance.



Mean Particle Size (Microns)	Percent By Weight	Percent By Particle Count
20	28	0.005
7.5	52	0.175
4.0	11	0.25
2.0	6	1.07
0.5	3	98.5

